


Explanation

- Monitoring Well
- ⊕ Public Water Supply Well
- ▲ Former Recovery Well
- ▲ Recovery Well
- ▲ Decommissioned Recovery Well
- ⊗ Non-Grace Recovery Well
- Former ReInjection Well
- ⋯ 2011 Institutional Controls Area
- Grace Property Boundary (approximate)
- ▭ 500 Foot Plume Buffer Zone
- Extent of Contamination (2018)
- ▭ 2689 Tax Parcel
- Town Boundary

- ⋯ Well Head Protection Zone 2
- ⋯ This area falls outside of the 500-foot Plume Buffer Zone, as mapped based on the Extent of Contamination in 2018. However, these parcels are in close proximity to the Landfill Area Treatment System, Sinking Pond, and the Town of Acton's Assabet Wellfield. Given the resulting complexity in predicting groundwater flow, and that groundwater contamination remains to the North, East, and South of this area, EPA recommends that the administrative hold restricting groundwater extraction be maintained on these parcels.

Extent of contamination includes areas with VDC, Vinyl Chloride, and/or Benzene concentrations greater than Interim Groundwater Cleanup Goals from samples collected in 2018.

DRAFT



TITLE: INSTITUTIONAL CONTROLS AREA	
LOCATION: W.R. Grace, Acton, Massachusetts	
	CHECKED: ED
	DRAFTED: JML
	DATE: 01/28/2020
FIGURE: 1	